Work Order ID 116375

Tuesday, April 15, 2014 10:52:25 AM

116375

Page 1

			711								
Item ID: Revision ID:	D3468-1			Accept	*N900	040	100)*	Setup Star	* *N	S1 *
Item Name:	Seal								Sto	, *VI	C2*
Start Date:	4/14/14	Start Qty: 2.00	*2*		Cust Item 1	D:				1 4	. 7/
Required Date	: 4/15/14	Req'd Qty: 2.00	*2*		Customer:	CVA	LH01				
Reference:	RMA RA111	712 - RETURN									
Approvals:	Process Plan	n:	Date: 1404-15	Tooling:	D:	ate:		/	Run Star	~1/1	R1*
	QC:		Date:	SPC (Y/N):	D:	ate:			Stop	, *N	R2*
Sequence ID/ Work Center I		Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revi	sion Nbr		DAS							
D3468	Rev	A		27							
100	1111		***	0.00					-,	·	
100				wold	γ_1			\Im			
QC		Memo		0.00 14141	0)						
Quality Control		INSPECT R D3468-1 B6									
				/							
110		Identify as per dwg & Sto	ock Location:	UG.00							
110								<u> </u>		61	112
Packaging		Memo		0.00				OX.	_	14.	-4-01
Packaging			GE USING NEW B/N								,
115		QC21- Final Inspection	Work Order Paleace	0.00							
115		2021- I mai mapecilon	WOLK OLDER RELEASE	0.00							71
QC Quality Control		Мето		0.00				<u>M</u>	し	14-04-	- [

M12 140451

DQA:			Date: _			WORK ORDER NON CONFORMANCE / LIDDATE										
QA Closed:			Date:			WORK ORDER NON-CONFORMANCE / UPDATE Work Order update only Work Order update only										
						DISPOSITION AGAINST DEPA					EPARTMENT	PARTMENT/PROCESS				
Work Orde	er: _												,			
						Rework			Skid-tube	Crosstube		Water Jet	Engineering			
Part N	۱٥					Scrap			Machining	Small Fab	_	d. Eng. Coor.	Quality			
						Use-as-is		Thern	noforming	Finishing	Rec/Stor	re/Packaging	Other			
NCR N	۱o. <u>-</u>					Suspected Unapproved	ч		Large Fab	Composite _		Supplier] []			
Root					Desci	ription of work order update	ı	nitial	Acti	ion	Sign &					
Cause	1	Date Step Qty				or non-conformance	Ch	ief Eng	Descri	iption	Date	Verification	QC Inspector			
Design																
Doc/Data																
Equip/Tooling																
Handling/Pre																
Material																
Operator																
Offset/Setup																
Process	Ш															
Supplier	Ш						1									
Training											:					
Transport	Ш															
Unapproved									<u> </u>							
							FA	ULT CA	TEGORY		. _ .					
Landi	ng G	iear				General	_	•		-		_	-			
		Bending				Bend		•	Program	<u> </u>	Outside Dim	<u> </u>	Pressure/Forced			
	Centre Not Concentric					BOM/Route		Grain	1		Over/Under	<u> </u>	Set-up			
	Cracks					Broken/Damage/Defect	L	Hardware			Part Incorre	<u> </u>	Temperature/Cure			
	Crimp/Kink/Ripple/Wave					Burrs	L	Inspection Incomplete/Unqualified		nqualified	Part Lost/Missing		Weld			
	Cuffs					Contamination	L	4	tions Incomplete/L	Jnclear	Part Moved		Wrong Stock Pulled			
	Crushing					Countersink		4	gned/off center		Positioned V	¬				
	Heat Treat					Cut Too Short	L	Mislab			Power Loss/	'Surge	Other			
	Inspection Strip in Tube					Drawing	\vdash	Misrea			-					
	Ш	Marks/Cl	natter		L	Drill Holes		Off-set								
		Turning S	equence			Finish		-	Calibration							
	Wave/Twist in Tube					Fit/Function	1	Out of	Sequence							

Tuesday, April 15, 2014 10:52:29 AM

Work Order ID: 116375

116375

Parent Item:

D3468-1

D3468-1

Parent Item Name: Seal

Start Date: 4/14/14

Required Date: 4/15/14

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP Rev: A New Issue 06-02-06 JLM

IPP Rev:B now made on water jet 08-10-22 DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3468-1		Manufactured	No				Each	1.0000		2			
D3468-1									**			, ,,,,,	

Location Loc Oty Loc Code ST046 89053

B66888 9 14.04.15 22

DQA: Date:						WORK ORDER NON-CONFORMANCE / UPDATE											
QA Closed:			Date:			WORK ORDER NON-CONFORMANCE / OPDATE Work Order update only											
						DISPOSITION		AGAINST DEPARTMENT/PROCESS									
Work Orde	er: _					Downer			Skid tubo Crosstub		1	Water Jet	Engineering				
Part No.						Rework Scrap Use-as-is	ı	Skid-tube Crosstube Machining Small Fab Thermoforming Finishing			d. Eng. Coor. re/Packaging Supplier	Quality Other					
NCR N	10					Suspected Unapproved		Large Fab Compos			J						
Root					Desci	ription of work order update	ı	nitial	Action		Sign &						
Cause		Date	Step Qty			or non-conformance	Chief Eng		Description		Date	Verification	QC Inspector				
Design																	
Doc/Data					i												
Equip/Tooling																	
Handling/Pre																	
Material													-				
Operator																	
Offset/Setup					İ												
Process									*								
Supplier																	
Training	Щ																
Transport	Ш																
Unapproved																	
							FAI	ULT CA	regory								
Landi					_	General	-	1			. .		-				
	-	Bending				Bend	Folio/Program			\vdash	Outside Dim		Pressure/Forced				
	Centre Not Concentric					BOM/Route		Grain			Over/Under	 	Set-up				
	Cracks					Broken/Damage/Defect	<u> </u>	4	Hardware		Part Incorrect		Temperature/Cure				
	Crimp/Kink/Ripple/Wave					Burrs		4	ion Incomplete/Unqualified		Part Lost/Missing		Weld				
	Cuffs					Contamination	_	4	tions Incomplete/Unclear	-	Part Moved	L.	Wrong Stock Pulled				
	Crushing					Countersink	\vdash	•	gned/off center	_	Positioned V		ا ا				
	Heat Treat					Cut Too Short	<u> </u>	Mislabe		L	Power Loss/	Surge	Other				
	Inspection Strip in Tube					Drawing		Misrea									
	-	Marks/Cl				Drill Holes	<u></u>	Off-set									
	-	Turning S	-		<u> </u>	Finish	_	4	Calibration								
	Wave/Twist in Tube					Fit/Function	1	IOut of	Sequence								